



## 2016 Connecticut State Building Code

### Errata #1

December 31, 2016

The following corrections are to be included as part of the code:

Table of Contents:	IECC – 109; NFPA 70 – 117; IRC - 123
Page 10	IBC 105.5 Exception should read: "...Section <b>116</b> ..."
Page 32	IBC Section 906 second item should read: "(Add) <b>906.2</b> Maintenance. ..."
Page 45	IBC Section 1023.6 should read: "...Penetrations into <b>and</b> openings through..." The exception is included in this section.
Page 50	IBC 1107.6.2.1.1 should read: "...ANSI A117.1-200 <b>9</b> ..."
Page 58	IBC Chapter 29 should be titled: PLUMBING <b>SYSTEMS</b>
Page 65	IBC 3109.4 Exception should read: "A residential spa or hot tub with a safety cover complying with ASTM F 1346 need not comply with Section 3109.4."
Page 116	IECC R403.2.2 Duct Tightness item #2: last sentence change 4 cfm to <b>3 cfm</b> .
Page 145	IRC R329.6.2: delete last sentence – "Cross-hatched portion shall not be shared between spaces."
Page 146	IRC Table R905.2.1.1(1): Left Heading should read "...APPENDIX <b>R</b> "
Page 156	NFPA Table: 720-12 should reference section R31 <b>5</b> .2